



BUCKET FORK INSTALLATION

1. Place forks on the ground.
2. Insert mounting bar through eyes of the forks.
3. Position top edge and bottom edge up against back of forks, approximately 3 inches below eye.
4. Hook bracket on mounting bar with flat face resting on top of bucket.
5. Tack mounting brackets in place; forged forks should hang below cutting edge of bucket.
6. Once all brackets are tacked in place, they should be welded solid to top of bucket using 7018 electrodes.

